TECHNICAL BULLETIN

S82 W18717 Gemini Drive
Muskego, WI, 53150
Phone: (877) 622-2694, Fax: (888) 679-3319
www.NabcoEntrances.com

Date: July 26, 2017

Who is the contact?
Technical Support Department

Please note the lock kit shown in Bulletin 50 below is no longer available

NABCO ENTRANCES TECHNICAL BULLETIN

S82 W18717 Gemini Drive
Muskego, WI, 53150
Phone: (877) 622-2694, Fax: (888) 679-3319
www.NabcoEntrances.com

Date: October 24, 2011

Who is the technical contact?
Alan Kettering

New Lock Kit for Older GT-1100 Sliding Doors

The original locks that were used with the older GT- 1100 sliding door system are no longer available. However, we have developed a new kit for retrofitting a new style lock to these doors.

The kit parts numbers are as follows: **21-13635 Kit for Fail Secure Lock**
21-13636 Kit for Fail Safe Lock

These kits also include a factory rebuilt and modified lock control (shown below). This lock control is required to operate the new lock. The new lock will not operate with the old control. The lock and control are available as a matched set as shown in the kit below. The modified lock control can be identified by a large *capacitor** located on top of the board which is not present on the old control (refer to illustration below).

Lock control wiring remains the same as before. Wiring diagrams and instructions are included in the kit. This lock kit will also work with the DS150/U30 Retro-fit Kit . Contact Technical Support for more information. Refer to the items shown below to see what is included in the new kit.

P/N 21-13635 Kit for Fail Secure Lock

P/N 21-13636 Kit for Fail Safe Lock



Mounting hardware, etc not shown for simplicity

Due to the fact that that the supplied lock control is a factory rebuilt control, a core charge will apply if the old control is not returned to Nabco.

Please contact Nabco Customer Service for more information.

Bulletin Number: **50**

Bulletin Number: **85**