

NABCO ENTRANCES TECHNICAL BULLETIN

Gyro Tech Lanson Parts Zone Gard
S82 W18717 Gemini Drive
Muskego, Wisconsin 53150
Phone: 1-414-679-0045
Fax (toll free): 1-888-679-3319

Effective Date: February 9, 1999

Who is the technical contact?
Nick Taguchi

Recommended Settings for the Folding Doors

We recently had a calls about a couple of folding doors that recycled more than they should. The problem was narrowed to growing friction in the mechanisms due to age and excessive speeds set in the microprocessor.

If you are experiencing unusual amount of recycles, we recommend you change the following settings:

OPEN SPEED: "0" or "1" or "2" with "2" being the maximum.

CLOSE SPEED: "0" or "1" with "1" being the maximum.

START POWER: "0" or "1" with "1" being the maximum.

CHECK: "0" or "1" with "1" being the maximum.

SENSITIVITY: "3"

If this does not solve the recycles, try applying a small amount of grease to the moving arms and rollers. If this does not solve the problem, the control box should be replaced.

Bulletin Number: 13
