

NABCO ENTRANCES TECHNICAL BULLETIN

Gyro Tech Lanson Parts Zone Gard
S82 W18717 Gemini Drive
Muskego, Wisconsin 53150
Phone: 1-262-679-0045
Fax (toll free): 1-888-679-3319

Effective Date: December 19, 2001

Who is the technical contact?
Michael L. Slosiarek

Telco Holding Beam Receiver (P/N 1410204-20)

A few customers have indicated they have experienced problems with the "Telco" brand holding beam sets when used for Breakout Shutdown or as a Safety device.

An examination of the holding beam kits in-house showed the "Telco" receiver was an (SMR 3306 S 2.5) PNP Normally Open - Dark Operated type instead of an (SMR 3106 S 2.5) NPN Normally Closed - Dark Operated type. Using the (SMR 3106 S 2.5) receiver will correct the problem and allow the holding beams to properly perform the Breakout Shutdown or Safety functions as intended.

Most units manufactured, in the past, have utilized "Optex" sensors which are not subject to this bulletin. A cursory investigation of a door system can easily identify the "Telco" product by the black colored snap-in sensor housings. The "Optex" sensor snap-in housings are clear plastic.

Since we are unsure of the quantity you may require, replacement receivers (P/N 1410204-20) should be ordered (cost free) through NABCO Entrances, Inc. Customer Service department (877-622-2694).

The SMR 3006 S 2.5 number was incorrect on the original bulletin number 27.

Bulletin Number: 27 Revised 12/19/01
