



Technical Bulletin

Date	Bulletin #	Model
02/09/2024	122	NABCO Swing (GT630)
Subject		
NABCO Swing Brake Stop Update		

Issue/Symptom

While the external brake stop in the NABCO Swing has performed well, NABCO's Research and Development team in concert with Technical Service have identified an opportunity to improve its performance under certain circumstances, for instance where there are high levels of stress on the brake stop.

Solution

A new Internal brake stop has been developed to better protect it from the more challenging applications.

This new internal brake stop will ship so the door will open less than 90°, the door should be adjusted open to final position as described in the newly revised installation manual.

An updated installation manual has been issued to describe new brake stop adjustment procedure.

Applicable Model Numbers

- All NABCO Swing (GT630)