


Date 1/17/2025	Bulletin # 126	Model Nabco Swing (GT630)
Subject Header Installation		

Issue/Symptom


- Holes for mounting the header may need to be drilled during installation. Metal shavings from the drilling process may fall onto the Opus control or behind the clear plastic cover. This can cause the Opus control to become inoperable.

Solution

- Nabco recommends during the install process of the header, one of two things can be done to prevent metal shavings from damaging the Opus control.
 - The Opus control can be removed from the brackets that secure it to the header prior to the drilling/installation of the header.



- The Opus Control can be pulled out and covered with a cloth





Beware of metal pieces when removing cloth

Applicable Model Numbers

- All Nabco Swing (GT630)

Contact

NABCO Entrances, Inc.

Technical Support Department
Techsupport@nabcoentrances.com
1-877-622-2694 Ext 3