



Technical Bulletin

Date	Bulletin #	Model
1/5/2025	130	GT1175 U30 models
Subject		
DS-150 operator end of life		

Issue/Symptom

The DS150 is no longer available for purchase as it has reached its end of life.

Solution

Purchase a retrofit kit to replace all components in the slide header.

The kits contain a VS-150 motor, motor mounting bracket, idler, belt brackets, belt and hardware. Install the retrofit kit to replace the obsolete DS-150 operator.

Retrofit kit part numbers:

- A-01423, Standard slide units
- A-01454, Telescopic slide units

Applicable Model Numbers

All GT1175 units containing U-30 components.

Contact

NABCO Entrances, Inc.

Technical Support Department
Techsupport@nabcoentrances.com
1-877-622-2694 Ext 3