

NABCO ENTRANCES TECHNICAL BULLETIN


NABCO Entrances, Inc.
S82 W18717 Gemini Drive
Muskego, Wisconsin 53150
Phone: 877-622-2694
Fax: 888-679-3319

Effective Date: July 17, 2007

**Contact the Customer Service Department
at 877-622-2694**

Swinger Arm Stop – Outswing Units

The arm stop used on GT710 and Sideload units was redesigned. This design change required a new longer fastener. The fastener needed for the new arm stop is a ¼-20 x 1 ½” Long Phillips Pan Head Type F Self Threading Fastener (24-4941-21). If you have received the arm stop and need the longer fasteners, please contact customer service. The fasteners will be shipped regular UPS at no charge or can be shipped with your next order. Our records show that the longer fasteners are needed on orders shipped with the new arm stop from 5/16/07 to 7/11/07.



Bulletin Number: 39
